


**PPE  
DOFFING  
(WITH HEADWEAR)  
STEP  
SIGNAGE**


# Step 1:

# Gloves OFF



1. Grasp outside of glove with opposite gloved hand; peel off
2. Hold removed glove in gloved hand
3. Slide fingers of ungloved hand under remaining glove at wrist
4. Peel glove off over first glove


# Step 2: Hand Hygiene



**Wash hands or use an  
alcohol-based hand rub**


Cover all surfaces of hands,  
rub hands until dry

# Step 3: Gown OFF



1. Undo fasteners or ties
2. Pull away from neck and shoulders, touching inside of the gown only
3. Turn gown inside out, away from clothing
4. Fold and roll away from the body

# Step 4: Hand Hygiene




**Wash hands or use an  
alcohol-based hand rub**

Cover all surfaces of hands,  
rub hands until dry

# **Step 5: Headwear / headcovering OFF**

# Step 6: Hand Hygiene



**Wash hands or use an  
alcohol-based hand rub**

**Cover all surfaces of hands,  
rub hands until dry**


# Step 7: Protective eyewear OFF



1. Handle by head band or inside arms
2. Put aside for cleaning if reusable




# Step 8: Hand Hygiene



**Wash hands or use an  
alcohol-based hand rub**


Cover all surfaces of hands,  
rub hands until dry

# Step 9: Mask OFF



1. **Do not** touch front of the mask
2. Use ear loops to gently lift, remove mask away from the face and body.

# Step 10: Hand Hygiene



**Wash hands or use an  
alcohol-based hand rub**

Cover all surfaces of hands,  
rub hands until dry